

Just Inspections

Building Inspection Service

Phone 1300 558 119
Email admin@justinspections.com.au
Website <https://www.justinspections.com.au>
ABN 23687620631



REPORT ON COMMERCIAL BUILDING WORK

SECTION 137B OF THE BUILDING ACT 1993 (OWNER BUILDER CONSTRUCTION)

Report Details

Report Date	08 Aug 2026
Structure At	
Document Prepared By	Reza Montazer
Licence Number	IN-U 100002 Registered Building Practitioner: Building Inspector - Unlimited

Client Details

Contact	
Address	
Contact Phone	

Weather Details**Overcast**

Temperature (Low / High)	8.5°C / 14.9°C
Humidity	69%
Wind Speed	9.33km/h
Wind Direction	NNE

1 Inspection Details

Construction

Main Building Floor Construction

-

Wall Material(s)

Double brick

Floor Material(s)

-

Roof Material(s)

Coloured metal sheeting

Pier Material(s)

-

Smoke Alarm

-

Fixed Appliances

-

Services & Utilities

- ☒ Electricity
- ☒ Sewerage
- ☒ Storm water drainage
- ☒ Water (mains)

Site Details

Site Description

Domestic building site with private dwelling

Site Location

West side of the street

Site Slope

Flat

Site Drainage

Adequate

Paving

Adequate

Boundary Fence

-

Trees

A few closer than mature height would allow.

(As a general rule trees should be no closer to a building than their mature height).

Areas Inaccessible at Time of Inspection

Inspection was carried out from standing on a 3.6 m ladder.

Condition & Status of Incomplete Works

-

List of Defects

-

General Notes

Please note due to height safety restrictions the inspection was carried out a standing position on the ladder only. Safe access to roof i.e. harnessing, scaffolding) was not available at the time of inspection.

Disclaimer

We have only inspected areas as instructed by the client. Any defects listed in the Owner Builder Report we recommend engaging a licensed tradesman eg carpenter, plumber, electrician, etc to provide further advice. The report is not a warranty against problems developing with the building in the present or near

future. The Owner-Builder states that no secondhand materials have been used in the project(s).

2 Detail Report: External

Inspected Area

Photos of Inspected Area



Roof repair work. New area of roof.



3 Conditions, Assumptions & Limitations

- This Report has been prepared and is provided pursuant to the provisions of Section 137B of the Building Act 1993 and in accordance with the special Government Gazette dated May 14, 1996. The Report is valid for a period of six (6) months from the date of the Report.
- This Report covers only building works carried out by the nominated Owner-Builder. Pre-existing works, or works carried out by others, is specifically excluded.
- The inspection of the property is a special purpose property inspection carried out in accordance with the recommendations for, and the limitations of, a visual inspection of residential buildings set out Australian Standards – AS 4349.1 – 2007 Inspection of Buildings Part 1: Property inspections – Residential buildings (hereafter referred to as “AS 4349.1”) except to the extent specifically varied herein.
- The report of the inspection of the property is a special purpose property report prepared in accordance with the recommendations and limitations and conditions set out in AS 4349.1 except to the extent specifically varied herein. It is not a guarantee that works are free from latent or other defects.
- The inspection is not a standard property inspection within the meaning of Section 2 of AS 4349.1.
- In the event that the client has requested a verbal report of the inspection from Just Inspections its servants or agents prior to being provided with the written report such verbal report is only provided as a summary or an extract of the final written report and such verbal report is not to be relied upon in isolation from, or in lieu of, the final written report.
- Only those parts of the residential building to which reasonable access (as defined in AS 4349.1) is allowed or permitted have been inspected.
- The Report is prepared from and based on a visual inspection only of such parts of the building(s) to which Just Inspections its servants or agents had reasonable and safe access, without moving or removing anything.
- No inspection of woodwork on parts of the structure which are covered, unexposed or inaccessible has been undertaken and therefore this report cannot be relied upon as an assessment that such part of the structure is free from defect.
- Normal or expected construction practices and building techniques that are considered typical of buildings of the age and design of the building have been assumed in the inspection and preparation of the report.
- No assessment has been made of any existing or future impact on the footings or foundations of the building or on the fabric or serviceability of the building works caused by site or ground drainage, trees or any other ground movement caused by swelling, shrinkage or other causes that may include settlement or movement of non-structural or filled ground.
- No assessment has been made of the site or soil, including landslip, or foundation upon which the building, works and or footings and associated building works have been constructed.
- No assessment has been made of any dampness in the building(s) as may have resulted from rising damp, stormwater infiltration or other causes or the likelihood of such dampness occurring other than that revealed by reasonable visual inspection.
- No assessment has been made as to the presence or otherwise of asbestos or other mineral fibre or any other toxic or other potentially harmful materials in the building or in any landfill.

4 Conditions, Assumptions & Limitations (Continued)

- Just Inspections, its servants and agents do not profess to have expertise in pest infestation (including termites and other timber pests). No assessment of pest infestation, or the potential of pest infestation, has been carried out. Nothing in this report should be relied upon as an assessment that the building is either subject to or free from pest infestation, or susceptible to or not susceptible to pest infestation. Just Inspections strongly recommend a specialist pest investigation be carried out.
- No assessment of electrical installations, smoke detectors, residual current devices, plumbing, drainage, gas fitting, air-conditioning, garage door operating mechanism, swimming pool or spa equipment, operation of fireplaces, flues or chimneys, alarm systems, intercom systems, soft floor coverings, appliances (including dishwashers, incinerators, ovens, ducted heating or vacuum systems), paint coatings or hazards has been made.
- No assessment of the matters described in Part 6 of the applicable Building Regulations including the potential for land to flood, be subjected to bushfire attack, or the potential of the building to be subjected to termite attack or the potential of the building to be subject to uncontrolled overland drainage flow has been made.
- No inquiries have been made of the Council or any other statutory authority or service, utility or supply agency.
- No assessment of the siting of the building has been made.
- No assessment of compliance with 4-, 5- or 6-star building regulations has been made.
- No testing of any material, equipment, fittings, fixtures, reticulated surfaces or appliances has been carried out.
- For the purposes of this Report the definition of 'Defect' is identified and described in Section 137C (1) of the Building Act 1993 and Section 8 of the Domestic Building Contracts Act 1995. Any 'Defect' will be regarded in the terms of the requirements and/or the expected practices at the time the Building Work was carried out or any applicable Approval or Building Permit was issued.
- The report, with any attached appendices, is copyright and remains the property of Just Inspections. No part of this report may be copied or reproduced without the prior written consent of Just Inspections.
- The agreement to carry out the inspection and provide the report is governed by and shall be interpreted in accordance with the laws of the State of Victoria and each party unconditionally submits to the jurisdiction of the Courts of Victoria and any Court competent to hear appeals thereafter.
- In the event that the client has not been advised of, or provided with, these conditions prior to receiving the report then should any or all of the conditions of inspection, service and report not be acceptable to the client, then such advice must be notified to Just Inspections in writing within 3 days of the date of this report, otherwise the client accepts all the conditions.
- --- END OF REPORT ---